

] Hand Delivered

MARYLAND DEPARTMENT OF THE ENVIRONMENT

LAND and MATERIALS ADMINISTRATION SOLID WASTE PROGRAM 1800 Washington Boulevard Suite 605 Baltimore Maryland 21230-1719

(410) 537-3315 • 1-800-633-6101 • https:// mde. maryland. gov

Report of Observation	ervations	
Inspector(s): Christopher Barlow	AI	#: 96927
Type of Inspection/Observations: Routine Inspection		ate: 5/31/2023
Site/Facility Name: Camp Small – Baltimore City Department o	f Parks & Recreation Tir	me In: 3:20pm
Location: Cold Spring Lane next to Jones Fall – Baltimore City	 Tir	me Out: 4:35pm
Contact(s): Facility Manager Shaun Preston, Nick Oster Inspection Reason: Routine Scheduled Site Status: Active Site Condition: Corrective Actions Required Recommended Action: Continue Routine Inspection Evidence Collected: Visual observations and photos (see pages be Weather: 79°F Clear No Precipitation Calm wind Field Conditions: Dry Remarks: I arrived at the facility and attempted to locate Facility Manager Shaun P of arrival. The logs on the northwest side of the access road have been place. I observed a stockpile of woodchips that was approximately 30ft to woodchips; the lower half of the stockpile was found to be 110°F-120°F, facility should turn the large stockpile of woodchips regularly to prevent a consider turning this one large pile into multiple smaller piles. The signs organize material onsite. The super silt fence is holding back multiple fall compromised at any point. The fire lane that runs from the main access log, all other fire lanes are clear of debris. After I completed my inspection, Nick Oster and Facility Manager Shaun facility's operations. They confirmed that the logs on the northwest side of inspection on 1/11/2023, and they stated that a clean up plan for more log informed them of the temperatures recorded in the large stockpile of woomultiple piles. Mr. Preston told me that the facility does not have a temperature of the woodchip stockpile. Summary: The accumulation of land clearing debris and natural wo "open dumping". Follow-up with the facility manager is needed; a shave been stockpiled on site for over a year should be established. Note: Operating without a permit or in violation of a permit or law menalties. Each day a violation occurs is a separate occurrence. Be such, is accessible to the public.	reston and Nick Oster, but no emoved, while the rest of the all. I measured the temperature observed during the last insplen logs from rolling into the croad to the southeast corner. Preston arrived onsite. I spoof the access road had been ags and the 30ft tall stockpile odchips and suggested that the enture reader, and thus were coded waste without timely prechedule for the removal of ay result in the assessmentadvised that this inspection	o one was present onsite at my time e logs that line the road remain in are of this large stockpile of e was found to be 140°F-164°F. The s; additionally; the facility should ection are being used to help Jones Fall River but is not of the property is blocked by a fallen ske with both of them about the removed since the previous of woodchips is in the works. I he pile be turned and split into e unable to measure the cocessing or removal constitutes all unprocessed materials that the of civil or administrative on report is a public record and as
Inspector: Christopher Barlow Jr Christopher Barlow Jr	Received by:	ativa/Deta
	Signa	ature/Date
Report provided to: Email Regular Mail Certified Mail		Name

1800 Washington Boulevard • Baltimore Maryland 21230 (410) 537-3000 • 1-800-633-6101 • http:// www. mde. state. md. us

LAND and MATERIALS ADMINISTRATION Report of Observations

Woodchip Pile












1800 Washington Boulevard • Baltimore Maryland 21230 (410) 537-3000 • 1-800-633-6101 • http:// www. mde. state. md. us

LAND and MATERIALS ADMINISTRATION Report of Observations

Access Road









1800 Washington Boulevard • Baltimore Maryland 21230 (410) 537-3000 • 1-800-633-6101 • http:// www. mde. state. md. us

LAND and MATERIALS ADMINISTRATION Report of Observations

Sorted Materials









1800 Washington Boulevard • Baltimore Maryland 21230 (410) 537-3000 • 1-800-633-6101 • http:// www. mde. state. md. us

LAND and MATERIALS ADMINISTRATION Report of Observations

Blocked Fire Lane





